



DEKRA Services Inc.
Customer Service 770-257-0107

USED EQUIPMENT

INSPECTOR: 5440
 INSPECTION ID
 102113

INSP DATE | VIN (LAST 8) | PO NUMBER
 09/25/2019 | 0000070 |

CONDITION REPORT

POWERTRAIN COMPONENTS		COMMENTS
OK	ENGINE	
N/A	PUMP DRIVE	
N/A	MAIN HYD PUMPS	
N/A	SWING PUMP	
N/A	TRAVEL MOTORS	
N/A	SWING MOTORS	
N/A	L FINAL DRIVE	
N/A	R FINAL DRIVR	
N/A	OTHER (SPECIFY)	
N/A	OTHER (SPECIFY)	
ATTACHMENTS		COMMENTS
N/A	BUCKET/BLADE	
N/A	COUNTERWEIGHT	
N/A	RIPPER DRILL	
N/A	OTHER (SPECIFY)	
N/A	OTHER (SPECIFY)	
FRAME & STRUCTURAL		COMMENTS
OK	CARBODY	
OK	MAIN FRAME	
N/A	TRACK FRAMES	
N/A	BOOM	
N/A	STICK	
N/A	BUCKET LINKAGE	
N/A	SWING ASSEMBLE	
N/A	OTHER (SPECIFY)	
HYDRAULIC COMPONENTS		COMMENTS
N/A	PUMPS	
N/A	MOTORS	
N/A	LINES & HOSES	
N/A	VALVES	
N/A	CYLINDERS	
N/A	LINKAGE/CONTROLS	
N/A	HYD OIL COOLER	
N/A	OTHER (SPECIFY)	
N/A	OTHER (SPECIFY)	
OUTSIDE INSPECTION		COMMENTS
OK	R.O.P.S.	
OK	CAB	
N/A	HYD TANK	
OK	FUEL TANK	
OK	CATWALKS	
OK	DOORS	
N/A	SWIVEL GUARD	
N/A	OTHER GUARDS	
N/A	OTHER (SPECIFY)	
N/A	OTHER (SPECIFY)	



DEKRA Services Inc.
Customer Service 770-257-0107

USED EQUIPMENT

INSPECTOR: 5440
 INSPECTION ID
 102113

INSP DATE | VIN (LAST 8) | PO NUMBER
 09/25/2019 | 0005070 |

CONDITION REPORT

IN-CAB INSPECTION		COMMENTS
OK	GAUGES	
OK	SWITCHES	
OK	ELECTRONIC DISPLAY	
OK	SEAT	
OK	CAB GLASS	
OK	DOOR LATCHES	
OK	WINDSHIELD/REAR WIPERS	
OK	HEATER	
OK	AIR COND	
OK	RADIO	
N/A	OTHER (SPECIFY)	

ELECTRICAL SYSTEM		COMMENTS
OK	BATTERIES	
OK	STARTER	
OK	ALTERNATOR	
OK	LIGHTING	
OK	BACK-UP ALARM	
OK	HARNESSES	
N/A	OTHER (SPECIFY)	

OPERATIONAL CHECKS		COMMENTS
OK	FLUID LEVEL	
OK	FLUID COND	
OK	FILTERS	
OK	FUEL LEAKS	
OK	OIL LEAKS	
OK	COOLANT LEAKS	
OK	STARTUP	
OK	SMOKE/BLOWBY	
N/A	AUTO ENG SPD CTRL	
OK	POWER MODE	
OK	NOISES	
OK	STARTING AIDS	
OK	TRAVEL	
OK	LINKAGES	
OK	SERVICE BRAKES	
N/A	SWING BRAKES	
OK	PARKING BRAKE	
OK	RADIATOR	
OK	WATER HOSES	
OK	BRAKES	
OK	TIRES/TRACKS	
N/A	HYD LEAKS	
N/A	OTHER (SPECIFY)	

Additional Services	Requested	Status	Comments



DEKRA Services Inc.
Customer Service 770-257-0107

USED EQUIPMENT

INSPECTOR: 5440
INSPECTION ID
102113

INSP DATE	VIN (LAST 8)	PO NUMBER
09/25/2019	0000070	

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS	PART COST (\$)	LABOR
TOTAL ESTIMATE			0
TOTAL (PARTS + LABOR)			0

COMMENTS:



DEKRA Services Inc.
Customer Service 770-257-0107

USED EQUIPMENT

INSPECTOR: 5440
INSPECTION ID
102113

INSP DATE | VIN (LAST 8) | PO NUMBER
09/25/2019 | 0005070



VIN/SERIAL NUMBER



LEFT SIDE



LEFT FRONT



FRONT



RIGHT FRONT



RIGHT SIDE



RIGHT REAR



REAR



LEFT REAR



LEFT REAR TIRE/TRACK



LEFT FRONT TIRE/TRACKS



RIGHT FRONT TIRE/TRACK



RIGHT REAR TIRE/TRACK



OPERATOR'S SEAT



ENGINE HOURS



LEFT SIDE CONTROLS



DEKRA Services Inc.
Customer Service 770-257-0107

USED EQUIPMENT

INSPECTOR: 5440
INSPECTION ID
102113

INSP DATE	VIN (LAST 8)	PO NUMBER
09/25/2019	0005070	



ENGINE DATA PLATE



LEFT SIDE ENGINE



RIGHT SIDE ENGINE



ADDITIONAL 1